NTSB | National Transportation Safety Board

CEN26LA185

INVESTIGATION PHOTOGRAPHS



Photograph 1 – Helicopter on helipad (FAA photo)



Photograph 2 – Helicopter on helipad (FAA photo)



Photograph 3 – Helicopter on helipad (FAA photo)



Photograph 4 – Tail boom / tail rotor (FAA photo)



Photograph 5 – Tail rotor assembly (FAA photo)



Photograph 6 – Tail rotor assembly (FAA photo)



Photograph 7 – Tail rotor assembly (FAA photo)